

**Call 10 Bridge Repair on SR 43 Relief Bridge No. 184.7, known as State Project No. EXB-0037-04(040) / 107139307 in Madison County.**

Q1. Note 4 on Sheet 8002 states, "Paint 5'-0" from the ends of the steel girders and the steel bridge railing." Painting only 5 LF of each girder end and 5 LF of each railing end with the affected posts only results in approx. 4,455 SF of steel to be painting. Can MDOT please explain where the remaining 5,800 SF of painting occurs?

A1. The estimated quantity was based on painting 5'-0" of the ends of the girders and the entire bridge railing, both sides, front and back.